

VW Tiguan — Avaria da luz durante a condução | HELLA

VWTiguan Ano de fabrico: 2008/01–2011/07 Avaria da luz durante a condução Nos veículos supramencionados, durante a condução, pode ocorrer repentinamente uma falha total ou parcial do sistema de iluminação. A causa para o problema supracitado pode dever-se a um fusível com defeito, no circuito de comutação da iluminação do veículo. O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados. Deve ter-se em consideração que, por diversos motivos, nem todos os veículos foram verificados ou reparados. Na oficina especializada, o fusível defeituoso é substituído por um fusível melhorado.

Tiguan

Model year: 01/2008-07/2011

Light failure while driving

The above vehicles may suddenly experience a partial or total failure of their lighting equipment while driving.

This problem may be caused by a defective fuse in the vehicle lighting circuit.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

The specialist garage will replace the defective fuse with an improved one on the vehicles in question.