

Citroen Jumpy IV + Spacetourer - Fastening the air conditioning compressor | HELLA

Citroen

Jumpy IV + Spacetourer

Model Year: 2016 – 2017

Fastening the air conditioning compressor

On the above vehicles, it is possible for the air conditioning compressor bracket to become loose and fall off.

The vehicle manufacturer has already recognized the problem and informed the affected owners. However, there is a possibility that for various reasons not all vehicles have been checked and/or repaired.

When carrying out service work on the vehicle, ensure that the compressor is firmly seated and that its bracket is firmly fastened.

The following production periods are affected.

Jumpy IV: 1/20/2016 - 3/3/2017

Spacetourer: 1/7/2016 - 3/4/2017