

# **Land Rover V6 - Contact between the DRS cable and the positive battery cable | HELLA**

**Land Rover**

**Range Rover Sport**

**V6**

**Model year: 2012**

**Vehicle Identification Number: LW000016 to -323768**

## **Contact between the DRS cable and the positive battery cable**

There may be contact between the DRS (dynamic response system) cable and the positive battery cable in the above vehicle.

The constant contact between the two cables may cause damage to the cable insulation.

The DRS cable may heat up when in contact with the positive battery cable, which can cause damage to the electronic components.

The vehicle manufacturer has already addressed the issue.

The cables are inspected for abrasion in the specialist workshop, and are replaced if necessary.

An additional clip is installed in the affected vehicles to ensure sufficient distance between the cables.