

# **BMW Series All Models - Driving-Dynamics Control Failure (DSC) | HELLA**

**BMW**

**Series: F10, F11, F12, F13, F18, F25**

**All Models**

**Driving-Dynamics Control Failure (DSC)**

**ESP Warning Light Comes On**

**Error code: 480A66**

There can be multiple reasons if the error message listed above is displayed in the instrument cluster, in combination with the Check Control message "DSC malfunction/Reduced vehicle stability". This error primarily occurs when the Auto Hold Function is active and when the vehicle is moving off. In certain cases, it can also occur through driver error, if they keep their foot on the brake pedal for too long when moving off (two-footed driving).

**Tests**

The following tests must be carried out to determine the cause:

- Check the brake pedal switch is fitted correctly and functions properly
- Check the function and the ability of the brake pedal to return to its position
- Check electric wiring and plug connections of the affected assemblies

Please also observe the repair notes provided by the vehicle manufacturer on this issue.

**Note**

If no defects have been determined, the ESP control unit software may be updated to correct the error.

Please inquire about this at an authorized garage.

## **Important safety note**

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.