



Vauxhall Insignia - poor acceleration behaviour under load

Data sheet	
Manufacturer	Vauxhall
Vehicle model	Insignia A
Engine	1.6i 16 V
Engine code	A16 LET
Year of manufacture	2009 - 2013
VIN	91008178 - C1056226
Symptoms	Poor acceleration behaviour under load

Important safety note

Poor acceleration behaviour - but no error code stored

If the above-mentioned defect is detected, it may be related to a software error in the engine control unit. If no other defects can be localised as the cause in the course of troubleshooting and during an ECU diagnosis,

a check should be run to determine how far a software update is available for the engine control unit.

A software update can be carried out, for example, via Hella-Gutmann macsRemote Services or by using a pass-through-capable diagnostic device from the mega macs series. Furthermore, registered access to the vehicle manufacturer's online portal is required. If the appropriate equipment is not available, please contact an authorised specialist workshop.

IMPORTANT

This defect may also occur in other models with the same type of engine.

Please always follow the repair instructions from the vehicle manufacturer when carrying out such work.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.