

# **Vauxhall Vivaro - Uncontrolled illumination of the ABS Service- Stop warning light while driving | HELLA**

**Vauxhall Vivaro**

**All models**

**Model years 2001-2003**

**Uncontrolled illumination of the ABS Service- Stop warning light while driving**

**No error code stored in the control unit**

If the above defect is noticed, the cause may be a faulty windshield wiper motor.

The windshield wiper motor creates interference which can result in malfunctions and illumination of the ABS warning light.

In case of repair, we recommend the following procedure: