

# **Volvo XC 90 II - Temperature control of air-conditioning system | HELLA**

**Volvo**

**XC 90 II (256)**

**Model year: 2016 - 2017**

**Temperature control of air-conditioning system**

## **Faulty display for outside temperature**

The vehicles mentioned above may have a faulty interior display for the outside temperature. This can also affect how the air-conditioning system is controlled. A faulty sensor in the outside mirror is the possible cause.

To fix the problem, the outdoor temperature sensor (in the housing of the right outside mirror) should be replaced with a modified version.

Vehicles with chassis numbers in the following range may be affected:

00000561 - 0143824 and 0042202 - 0143824