

# Vauxhall Ampera - Battery charging cable deformed | HELLA

**Vauxhall**

**Ampera**

**Engine: 1.4i 16V Hybrid**

**Model year: 2012**

**Chassis number: ...CU105113 - ...CU128385**

## **Battery charging cable deformed**

A faulty battery charging cable on the above vehicles may result in overheating and deformation up to the point of melting the charging cable.

As a result of the described issue, the battery will no longer be sufficiently charged or will not charge.

### **Note:**

When working on high voltage components (HV), it is absolutely essential that the complete vehicle electrical system is switched off and voltage-free beforehand. Only specially qualified persons may carry out this work (experts in working on HV intrinsically safe systems in vehicles).

Repair note:

Check the battery, connections, and charging cable for damage and replace if required.

A modified charging cable is available via the vehicle manufacturer.

OE article number: 23 453 436