

Opel Vivaro - Uncontrolled illumination of the ABS Service- Stop warning light while driving | HELLA

Opel Vivaro

All models

Model years 2001-2003

Uncontrolled illumination of the ABS Service- Stop warning light while driving

No error code stored in the control unit

If the above defect is noticed, the cause may be a faulty windshield wiper motor.

The windshield wiper motor creates interference which can result in malfunctions and illumination of the ABS warning light.

In case of repair, we recommend the following procedure: