



# BULLETIN

---

## **Peugeot Model: 307 Model year: from 2006 All models with ABS/ESP**

### **ABS warning light illuminates**

**Error code: 53768**

### **Faulty CAN communication**

If the error mentioned above is identified in conjunction with an illuminated ABS warning light, a faulty power supply to the ABS/ESP control unit may be one possible cause.

In this case, verify that the power supply, plug connections and wiring on the ABS control unit are faultless.

### **Repair note**

In this situation, check the vehicle battery at the same time. A faulty or exhaustively discharged battery may also be the cause of the error.