Bulletin



© Hella KGaA Hueck & Co., Lippstadt 29. März 2004 1-1

Opel Sintra from model year 1997 with 2.2 I engine

Poor engine running, noises, vibrations, idling fluctuations and lack of performance

If there are complaints with this vehicle that the engine does not run well, causes noises and vibrations, fluctuates when idling and lacks performance, one possible cause could be a faulty or incorrectly fitted gasket for the exhaust gas recirculation valve.

To eliminate the fault, check the air-tightness of the exhaust gas recirculation valve and replace the gasket if necessary.

