Bulletin



© Hella KGaA Hueck & Co., Lippstadt 26 January 2007 1-1

Citroen C3 All models with petrol engine

Engine judders and stops.

If there are complaints with these vehicles that the engine judders and/or stops, one possible cause is an interruption in the plug connection between the crankshaft speed sensor and the connection cable. Due to poor plug locking, an interruption occurs, leading to the above-mentioned faults. In order to eliminate the fault, an additional clamp must be fitted on the plug connection, in order to avoid renewed loosening. The additionally required clamp can be obtained via authorized dealers.



