



Opel Vivaro model year 2001 to 2003

Malfunction of displays, warning lights and the central locking system

If there are complaints about the above-mentioned faults, a faulty bodywork electronic module (BCM) could be the cause. A faulty capacitor in the BCM causes, amongst other things, the central locking system to be activated although the key is still in the ignition. In addition, an excessively high current consumption can be determined. This situation is caused by electrical components which do not switch off despite the "ignition off" state.

In this case the BCM must be replaced.

Bulletin