

© Hella KGaA Hueck & Co., Lippstadt

5. Dezember 2005

Honda Civic Model year 1995 - 2001

Failure of and/or water penetration near the interior lamp.

If there are complaints with these vehicles that the interior light has failed and/or water penetrates near the interior light, one possible cause is a leaky seal around the roof aerial. If the attachment screw is tightened with too much torque, the seal underneath the aerial base becomes damaged and the above-mentioned faults occur. To eliminate the fault the seal needs to be replaced.

Make sure when mounting the aerial that the attachment screw is not fastened too tight.



