



Noise emitted in the area of the vehicle auxiliaries drive system

1.9 TDI engines with tensioning arm (OE no.): 038 903 315 AE

Models:

Audi: A3

Ford: Galaxy

Seat: Alhambra, Ibiza IV, Leon, Toledo II

Skoda: Octavia

VW: Bora, Golf IV, Multivan T5, New Beetle, Sharan, T5

In the case of replacement of the ribbed V-belt and the tensioning and deflection rollers due to noise emission it is recommended as a rule to also replace the generator free wheel.

Due to heavy dynamic movement of the ribbed V-belt, noise may be emitted in the case of this engine. However, following the replacement of the ribbed V-belt and the tensioning and deflection rollers, the noise may persist in some cases. In such a case, the generator free wheel should also be replaced because the reduction of the vibration and the tension peaks in the belt considerably relieves the auxiliaries drive.

