Honda- Skurende og bankende støj omkring forruden | HELLA

HondaLegendMotorkode: J35A8 og J37A3Stelnr.: fra JHMKB16*7C204109Skurrende og bankende støj omkring forrudenHvis ovenstående fejl konstateres, kan det skyldes forrudens viskersystem og/eller viskerbladene.I dette tilfælde skyldes støjen en defekt vinduesviskerarm (i førersiden).ReparationsanvisningKontrollér først vinduesviskermekanismen for andre funktionsfejl, og reparer den om nødvendigt.Udskift vinduesviskerarmen samt viskerbladet (i førersiden) efter bilproducentens angivelser.Reservedele:- Vinduesviskerarm (højrestyret) OE-nr. 76600-SJA-E02- Vinduesviskerarm (venstrestyret) OE-nr. 76600-SJA-G02- Viskerblad (højrestyret) OE-nr. 76620-SJA-E02- Viskerblad (venstrestyret) OE-nr. 76620-SJA-G02Derefter bør der foretages en prøvekørsel for at kontrollere, at reparationen er udført korrekt.BEMÆRK:Vær i den forbindelse opmærksom på, at disse arbejder kun bør udføres af et autoriseret værksted, og at køretøjsfabrikantens reparations- og vedligeholdelsesanvisninger skal overholdes!**

Legend

Engine code: J35A8 and J37A3

VIN no.: from JHMKB16***7C204109

Scratching and knocking noises in the area of the windshield

If the above-mentioned problem is detected, one possible cause may be the windshield wiper system and/or the wiper blades.

In such a case a faulty wiper arm (on the driver's side) is responsible for the noise generation.

Repair notes

First inspect the windshield wiper mechanism in order to check for any other form of malfunctioning and then repair if necessary.

Replace windshield wiper arm and also the wiper blade (on the driver's side) in accordance with the vehicle manufacturer's instructions.

Spare parts:

- Wiper arm (right) OE no. 76600-SJA-E02

- Wiper arm (left) OE No. 76600-SJA-G02

- Wiper blade (right) OE No. 76620-SJA-E02

- Wiper blade (left) OE no. 76620-SJA-G02

Finally a test drive should be undertaken in order to run a check on the repair work.

IMPORTANT:

Please note that such repair work should only be carried out by an authorized specialist workshop and that the vehicle manufacturer's repair and maintenance instructions are to be observed!

Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.