Mercedes Benz G-klasse - Nedsat bremsevirkning på baghjulene | HELLA

**Mercedes BenzG-Klasse (463)Årgang: 12.2017 - 04.2018Nedsat bremsevirkning på baghjuleneHvis ovenstående fejl konstateres, kan det skyldes en revnet bremsecaliperholder på bagakslen.
I uheldigste fald kan det medføre, at bagbremsen ikke fungerer.Reparationsanvisningl tilfælde af kundeklage skal bremsecaliperholderen kontrolleres for mekaniske skader og evt. udskiftes.Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettede.I tilfælde af reparation anbefales det på forhånd at kontakte en autoriseret forhandler for at afstemme reparationsproceduren.**

Model years: 12/2017 - 04/2018

Poor braking function of rear-wheel brake

If the problem mentioned above is detected, this may be due to a torn rear axle brake caliper. In worst case scenario, the rear-wheel brake might fail.

Repair notes

In case of a customer complaint, check brake calipers for mechanical damage and replace where necessary. The vehicle manufacturer has already addressed the issue and notified the owners as required. In case of repair, we recommend contacting an authorized dealer first for coordinating repair handling.