BMW i3 (I01) - Interrupted radio reception | HELLA

BMW

i3 (I01)

Model year: 2013

Interrupted radio reception

When such a repair is required, the customer complains that the radio reception fails completely or that it is interrupted.

Troubleshooting:

An error code query using a suitable diagnostic unit showed that no error codes had been stored.

On closer inspection of the roof antenna unit, it was discovered that the antenna rod was damaged (a cracked or broken threaded rod), a situation which could lead to the above-mentioned problem.

Remedy:

- Disassemble the antenna rod

- Check the thread on the antenna rod (see photo) and also the thread in the roof antenna unit for damage and repair or replace if necessary.

- Mount the new antenna rod

- Check functioning of the radio



-Antenna rod OE No. 65209355718

Caution: Electric vehicle!

High-voltage components - risk of accident and injury (electric shock)!

Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.