Fiat Punto 176- - Failure of the rear lights or direction indicators | HELLA

Fiat Punto 176

All

Burnt / corroded connector contact on rear light

Failure of the rear lights or direction indicators

On the above mentioned vehicles, the rear lights and/or direction indicators may fail.

If the related bulb is in order, the electrical contacts and also the contacts on the connector should be checked for signs of burning.

Signs of burning (see figure) are mostly caused by a loose contact (insufficient force between the contacts).

To rectify the problem the contacts can be cleaned and, if possible, adjusted; if necessary the connectors are to be renewed.

