



Opel - TPMS fault lamp is permanently on

Data sheet

Manufacturer	Opel/Vauxhall
Vehicle model	Zafira Tourer C (P12)
Engine	1.6 100 KW
Engine code	D 16 SHJ
Year of manufacture	2011-2019
Symptoms	The TPMS fault lamp is permanently on
HELLA parts to replace	6PP 358 139-261

Important safety information

The tyre pressure warning lamp cannot be reset

In the case of the vehicle mentioned above, it may happen that,

following a repair to the tyre pressure monitoring system or a wheel change, the tyre pressure warning lamp cannot be reset and therefore does not go out.

One possible cause in this case may be that the tyre load

(Light/Ecco/Max) has not been set or saved in the instrument cluster.

This can be changed using the left-hand combination switch/indicator lever on the steering wheel as follows.

(Light, Ecco, Max)

Then confirm the setting on the indicator lever using the Set/Clr button.

ⓘ Please note

We recommend that, whenever you adjust the tyre pressure to suit the vehicle's load condition, you also adjust the setting on the instrument cluster.





Reifenbelastung

☒ Leicht

☐ Eco

☐ Max

Zurück



102575 km

R