

Honda Civic VII - Désinfection du vaporisateur | HELLA

Honda

Civic VII

Années de fabrication : 2001 à 2005

Echange du filtre d'habitacle

Désinfection du vaporisateur

Pour atteindre le filtre d'habitacle et réaliser une désinfection du vaporisateur aux véhicules ci-dessus, il faut procéder comme suit :

- Démonter la boîte à gants (figure 1)
- Enlever le couvercle du caisson de ventilateur (figure 2)
- Sortir le filtre d'habitacle (figure 3)
- Insérer une lance de pulvérisation pour désinfecter la surface du vaporisateur (figure 4)









Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.