Honda Civic VII - Sustitución del filtro del habitáculo | HELLA

Honda

Civic VII

Fecha de fabricación: 2001 - 2005

Sustitución del filtro del habitáculo

Desinfección del evaporador

Para poder acceder hasta el filtro del habitáculo en los vehículos arriba mencionados y para poder desinfectar el evaporador deberá procederse de la siguiente manera:

- Desmontar la guantera (imagen 1)
- Retirar la cubierta de la caja de ventilación (imagen 2)
- Sacar el filtro del habitáculo (imagen 3)
- Introducir el brazo difusor del aerosol para desinfectar la superficie del evaporador (imagen 4).









Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.