

Ford Focus - Illumination of the malfunction indicator lamp | HELLA

Ford

Illumination of the malfunction indicator lamp

Illumination of the malfunction indicator lamp

Year of manufacture from 5/2005 to 1/2007

P2135:

PCM/throttle/accelerator pedal position sensor switch A/B voltage ratio

P2135:

- Clean plug contact of throttle potentiometer.

P2135:

- To replace the potentiometer, remove the throttle housing and install the new potentiometer.

