Audi A3 - Heat output too low | HELLA

Audi

A3

Model years 1997 to 2003

All engines with cast-iron cylinder block

If a customer complains about the above error, this could be caused by contaminated engine coolant.


Reiniger für Kühlsysteme
cleaning agent for cooling
Nettoyant pour systèmes
de refroidissement
Reiniger voor koelsystemen

Such contamination (rust, metal particles from the cast-iron block) blocks the small openings in the heat exchanger preventing flow.