Lancia Ypsilon 843 - Malfunction "Third stop light" | HELLA

Lancia

Ypsilon 843

Model years: 2003 – 2011

If the Lancia Ypsilon (Fig.1) is found to have a fault or partial failure (Fig.2) affecting the "third" stop light, the possible cause may be individual defective light sources.

Malfunction "Third stop light"



Fig.1

Repair notes

We recommend the following procedure:

- Completely switch off the electrical system.
- Remove the faulty stop light. To do so, remove the covers (Fig.3) and unlock the clips (Fig.4).
- Then remove the light unit (Fig.5) and unplug the connector.

Fig.2





Fig.3



Fig.4



Fig.5

- Disconnect the bulb holder from the housing
- Remove the faulty bulbs and replace
- Re-assemble the third stop light in reverse order and install.

Then carry out a function test.

Then carry out a function test.

Spare parts required: 8GP 938 026-001 (W 2.3 W)

Note

To ensure a constant light pattern, we recommend replacing all bulbs in this situation.

Fig.6





Fig.8