Mercedes Benz G-Class - Poor braking function of rear-wheel brake

Mercedes Benz G-Class (463)

Model years: 12/2017 - 04/2018

Poor braking function of rear-wheel brake

If the problem mentioned above is detected, this may be due to a torn rear axle brake caliper. In worst case scenario, the rear-wheel brake might fail.

Repair notes

In case of a customer complaint, check brake calipers for mechanical damage and replace where necessary. The vehicle manufacturer has already addressed the issue and notified the owners as required. In case of repair, we recommend contacting an authorized dealer first for coordinating repair handling.