Volkswagen Eos - Interior lighting activates while driving | HELLA

Volkswagen

Eos

Model years: 05/2006 – 11/2010

Interior lighting activates while driving

If the indicated problem occurs in above vehicle, a malfunction of the hazard warning switch might be a possible cause.

The central locking system might also be malfunctioning -- it unlocks and locks by itself while driving --

Repair notes

- Check control unit for central locking system for possible error memory entry. (Error code: 0556/ unlocking triggered by crash signal)

- Check airbag control unit for possible error memory entry.

- Check electric connection cable central locking system control unit.

- Check electric connection cables of airbag control unit.

Remedy:

Check hazard warning switch functionality and replace if necessary.