Honda Civic VII - Disinfezione dell'evaporatore | HELLA

Honda

Civic VII

Data di costruzione: 2001 - 2005

Sostituzione del filtro abitacolo

Disinfezione dell'evaporatore

Su questi veicoli, per accedere al filtro abitacolo ed effettuare una disinfezione dell'evaporatore, procedere come segue:

- Smontare il vano portaoggetti (figura 1)
- Rimuovere la copertura della scatola ventilatore (figura 2)
- Estrarre il filtro abitacolo (figura 3)
- Inserire il beccuccio nebulizzatore per la disinfezione della superficie dell'evaporatore (figura 4)

Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.