Mercedes Benz Classe G - Ridotta azione frenante del freno della ruota posteriore | HELLA

Mercedes Benz

Classe G (463)

Data di costruzione: 12.2017-04.2018

Repair notes

In case of a customer complaint, check brake calipers for mechanical damage and replace where necessary. The vehicle manufacturer has already addressed the issue and notified the owners as required. In case of repair, we recommend contacting an authorized dealer first for coordinating repair handling.