



Opel Mokka - Modified starting torque for wheel nuts

Data sheet	
Manufacturer	Opel
Vehicle model	Mokka
Engine	All models
Year of manufacture	2013 -
Symptoms	Modified starting torque for wheel nuts

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Please note the changed tightening torque when mounting the tyre

The cited starting torque for wheel nuts has been changed from 125 Nm to 140 Nm.

Please observe the modified starting torque when mounting tyres.

The vehicle manufacturer has already addressed the issue and the values have been changed to 140 Nm in Tis2Web (technical information system).

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.