

Product information - Combined brake caliper TEVES

Changed brake pads

8DB 355 009-121 / 8DB 355 011-731

Old: 8DB 355 009-121 / T1215

The brake pad on the piston side with version 8DB 355 009-121 / T1215, has been fixed to the piston using clasps (A) "Mouse traps" for the purpose of avoiding noise and vibration. The technician must practice great care when assembling.

Resulting from assembly faults, the clasps do not engage completely on the piston which leads to extreme tilted wear and increased noise levels.

Some vehicle manufacturers have reworked this system and have introduced a changed brake pad.

New: 8DB 355 011-731 / T1489

The equipment of the new brake pad differs significantly from its original version but can be used without question.

Note:

Brake pads with retaining spring (B) must be installed in the brake caliper on the piston side.

Vehicle models affected

Opel /GM

Signum, Vectra

Ford

Focus

Nissan

Primera

Citroen

C5

Mazda

3, 5

Renault

Espace, Laguna II, Vel Satis

Saab

9-3

Note:

This product replacement does not take place with all Renault and Nissan models. Please observe the respective product allocations in the catalog.

Figures

