

Audi A6/A8 - Warning in the instrument cluster | HELLA

Audi

A6/A8

Model year: from 2000

Warning in the instrument cluster

(defect in electronic chassis).

Following a visit to a garage, the hazard warning light for the electronic chassis (adaptive air suspension) may come on in the instrument cluster. The error message may occur if the vehicle was raised on the lifting platform for a longer period of time.





Adaptive air suspension