



BMW 1 Series/3 Series/4 Series - Smell of fuel in the vehicle interior / passenger compartment

Data sheet	
Manufacturer	BMW
Vehicle model	1 Series / 3 Series / 4 Series
Model series	F20 / F30 / F31 / F32 / F33/ F34 / F35 / F36
Engine	N47
Year of construction	2013
Symptoms	Unpleasant odour (fuel smell) in the vehicle interior / passenger compartment

Important safety note

BMW 1 Series/3 Series/4 Series - Unpleasant odour in the vehicle interior / passenger compartment (fuel smell)

In this repair case, the customer complains of an unpleasant odour (fuel smell) in the vehicle interior / passenger compartment.

The cause of the above-mentioned problem is a leaky fuel line.

Remedy: Replace the fuel line in accordance with the vehicle manufacturer's instructions.

After completion of the repair work, it is essential to check the fuel supply system and all connections for leaks before starting the engine and driving off.

Spare parts required	OE part number
Fuel supply line (1x)	13 53 8 594 893
Hose clamp (1x)	11 15 1 727 509
Torx screw (4x)	07 14 7 270 121

IMPORTANT

Please note that such work should only be carried out by an authorised specialist workshop and that the vehicle manufacturer's repair and maintenance instructions must be observed!

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.