

Opel Astra H - Condenser damaged and leaking | HELLA

Opel

Astra H

Model year: 2002 - 2009

Loss of refrigerant

Condenser damaged and leaking

If refrigerant loss is observed on one of the vehicles listed above, special attention should be paid to the condenser.

Failure of the fins can cause instability in the condenser network. Vibrations can cause contact with other components. This will damage the condenser (Figure 1) and, in some cases, cause it to leak.

The condenser may also come loose from its holder and drop onto the beam (Figure 2). This can also cause leaks.




Figure 1



Figure 2

ⓘ Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.