

Opel Astra J - Electric parking brake indicator lamp illuminates, brake light flickers | HELLA

Opel

Astra J

Model year 2010-2011

All Models

Electric parking brake indicator lamp illuminates, brake light flickers

Error code C0277 "Brake pedal sensor current circuit"

Error code C0277

If the error above occurs and error code C0277 is read out of the Body Control Module (BCM) at the same time, the brake pedal position sensor could be a possible cause of the malfunction for this.

In this case, the installation position and the calibration of the pedal sensor must be checked.

After a removal or installation, or renewal of the brake pedal position sensor, a calibration must be carried out in BCM using an appropriate diagnostic unit. This procedure serves for determining the zero position of the sensor.

Calibration procedure

- Actuate the parking brake
- Set automatic transmission to "P" (if available)
- Connect diagnostic tester, e.g., Mega Macs 66
- Read-out and delete the error codes