

Opel Zafira B - Loss of coolant | HELLA

Opel

Zafira B

Model year: 2005 - 2010

Engine: 1.7 CDTi + 1.9 CDTi

In the above vehicles with small charge air coolers (Figure 1), the charge air cooler bracket can rub on the radiator and cause coolant loss (Figure 2).



Figure 2



When installing a new radiator, the charge air cooler bracket must be mounted so that new damage to the radiator can be ruled out.

