

Volkswagen Polo - Heating/air conditioning temperature control | HELLA


Volkswagen

Year of manufacture: 2001 - 2009

With automatic air conditioning

Heating/air conditioning temperature control

If there are problems with the temperature control of the heating or air conditioning in the above vehicles, a faulty evaporator temperature sensor (Fig. 1) may be responsible.



TIP: Aids such as an optical square and flexible inspection lamp facilitate disassembly/assembly





Figure 3

