

Volvo

Volvo V70

Radio interference by disturbance from the fuel pump ass'y

Radio interference by disturbance from the fuel pump ass'y

If there are complaints about radio interference in the AM band in these vehicles, a possible cause of fault is the fuel pump ass'y.

- Check whether the signal interference is caused by the fuel pump ass'y.

If so, the vehicle manufacturer provides the interference suppression ring (spare part no. 30739380).

