

- #####
|

#####

#####

15

#####

#####.

#####.

#####

#####

#####)

#####!



#####

The following vehicles are affected.

Model codes: NDE180, NRE180, NRE185, WWE185, ZRE181, ZRE182, ZRE185 and ZWE186

To remedy the defect, the following OE spare parts have been offered by the vehicle manufacturer as part of a corrective measure:

- Brake calliper carrier 47721-09560

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only. Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.