

Renault Trafic - MIL (malfunction indicator lamp / engine warning light) comes on during longer downhill journeys | HELLA

Renault

Trafic

Model Year: 2011 – 2013

Engine: M9R-630

MIL (malfunction indicator lamp / engine warning light) comes on during longer downhill journeys

Fault codes: P0201 - P0204

Electric circuit, injection valve, cylinders 1 - 4

If the fault described above occurs together with the listed error codes, a possible cause may be defective software in the engine control unit.

As a result of faulty calibration of the engine control unit, the above-mentioned error codes can be triggered too soon.

Remedy:

First of all, read out the error memory and delete the fault codes. Recalibrate the engine control unit with the improved software (237613537R).

Finally a test drive should be carried out and the error memory read once again.

In such cases, please contact an authorized workshop.