

BMW F33 - no sound output

Data sheet	
Manufacturer	BMW
Vehicle model	F33
Engine	2.0i
Engine code	N20
Year of manufacture	2015
Symptoms	No audio output and also no acoustic warnings
Recommended tool	mega macs X

Important safety note

Permanent loss of sound and sloshing noises in the vehicle interior

With the above-mentioned vehicle type, it can happen that the entire sound output in the car fails. And sloshing noises can also be heard in the vehicle interior while the car is being driven.

(i) Please note

Please always observe the maintenance and repair notes provided by the vehicle manufacturer when carrying out such work and checks!