

Information sur le produit - Garnitures de freins Toyota | HELLA

Garnitures de freins Toyota

8DB 355 014-881 remplace 8DB 355 013-741

Nouvelle affectation des garnitures de freins

Due à une modification de l'équipement série par le constructeur automobile Toyota, l'affectation suivante des articles a été adaptée comme suit.


La garniture de frein 8DB 355 013-741 / T1747 est remplacée par la garniture de frein 8DB 355 014-881 / T1905.

Indication

Le stock existant de l'article 8DB 355 013-741 / T1747 peut encore être vendu.

Note de montage

La différence visible entre les deux garnitures de freins est dans la forme modifiée de la garniture de friction (A).



Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.