

Audi A3 - Heat output too low | HELLA

Audi

A3

Model years 1997 to 2003

All engines with cast-iron cylinder block

If a customer complains about the above error, this could be caused by contaminated engine coolant.

Reiniger für Kältsysteme
cleaning agent for cooling systems
Nettoyant pour systèmes
de refroidissement
Reiniger voor koelsystemen
Limpiador de sistemas de
refrigeración
Detergente per sistemi d'



Such contamination (rust, metal particles from the cast-iron block) blocks the small openings in the heat exchanger preventing flow.