

Dacia Logan - ABS warning lamp not functioning | HELLA

Dacia

Logan

Model year: May 2008 - January 2008



A problem in the instrument cluster may prevent a failure in the ABS system from being displayed. Even during the self-test, after turning on the ignition, the ABS warning lamp does not light up (see figure).