

Alfa Romeo 159 - Dårlig kølevirkning af klimaanlæg| HELLA

Alfa Romeo Type: 159 Alle modeller Dårlig kølevirkning af klimaanlæg
Kompressoren kobles til og fra konstant Hvis ovennævnte fejl forekommer på denne model, kan det skyldes en fejl i klimaanlæggets tørrefilter. Nedsat gennemstrømning i denne komponent kan ved høje temperaturer medføre stigende tryk, hvorved kompressoren kobles fra. I så fald skal man først kontrollere mængden af kølemiddel i systemet. Hvis mængden er korrekt iht. bilfabrikantens angivelse, skal tørrefilteret (A) ved kondensatoren udskiftes. (Hella artikelnummer: 8FT 351 335-141) Derpå skal det kontrolleres, at klimaanlægget virker korrekt. Bemærk: Følg i denne forbindelse bilfabrikantens generelle anvisninger om fejlfinding i klimaanlæg samt monteringsanvisninger.

Type: 159

All models

If the fault mentioned above occurs on this vehicle model,

the problem may be related to a defect

on the filter drier for the air conditioning system. A lack of porosity in this part results in a pressure increase at high exterior temperatures, as a consequence the compressor is switched off. In this case the amount of refrigerant in the system should be checked first. If the amount of refrigerant in the system is in accordance with the information from the vehicle manufacturer, the filter drier (A) on the condenser should be replaced.

(Hella article number: 8FT 351 335-141) Then check the air conditioning system for correct function.

Note: In relation to this aspect please follow the general information on diagnostics for troubleshooting air conditioning systems and the installation instructions from the vehicle manufacturer.

