

Audi Cabriolet - Utilstrækkelig lysstyrke| HELLA

AudiCabrioletÅrgang: 2003 - 2004Med xenonlygterUtilstrækkelig lysstyrkeFor ovennævnte biler klages der over reduceret og utilstrækkelig lysstyrke i forlygterne.Årsagen til problemet er i dette tilfælde fejl i belægningen af forlygternes parabler.Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.Værkstedet udskifter de defekte forlygteparabler i de berørte biler.

Cabriolet

Model year: 2003 – 2004

With xenon headlamps

Insufficient light output

On the vehicles mentioned above, customers have complained that the headlamps produce a reduced and insufficient light output.

The reason for this problem is a faulty coating on the headlamp reflectors.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

When the affected vehicles are taken to a specialist garage, the faulty headlamp reflectors are replaced with new ones.