

BMW 7-Serie - Bremserne hylér | HELLA

BMW 7-serie E 65/66 Alle modeller Årgang 2001 - 2008
Bremserne på for- og baghjul hylér ved let aktivering af bremserne. Hvis ovennævnte fejl konstateres, kan årsagen ligge i slidindikatoren for bremsebelægningerne. Ved let aktivering af bremserne kan advarselskontakten slæbe mod bremseskiven og generere en ubehagelig hyletone. I så tilfælde skal advarselskontakterne kontrolleres og evt. udskiftes med allerede ændrede versioner. OE-reservedelsnummer:
Advarselskontakt foran 34356778037 Advarselskontakt bag 34356778038 Reservedelsnummer HELLA
Advarselskontakt for bremsebelægninger, forhjul 8DK 355 250-201 Advarselskontakt for bremsebelægninger, baghjul 8DK 355 250-531 Reparationsanvisning
I denne forbindelse anbefales det at kontrollere bremseskiver og bremseklodser for slid og udskifte dem om nødvendigt.

7 Series E 65/66

All models

Model year 2001–2008

Front and rear axle brake system squeals when applying light braking force

If the above fault occurs, it may be associated with the brake lining wear indicator. When applying light braking force, the thermal contact on the brake disk may drag, thereby causing an unpleasant squeal. In this case, the thermal contacts must be checked and, if required, replaced with the new versions.

OE part number: front thermal contact 34356778037

rear thermal contact 34356778038

HELLA spare part numbers

Brake lining thermal contact, front axle:

Brake lining thermal contact, rear axle:

Repair note

In this case, it is advisable to check the brake disks and brake linings for wear and, if necessary, replace them.