

# **Citroën Jumpy IV + Spacetourer - Fastgørelse af klimakompressor HELLA**

**Citroën Jumpy IV + Spacetourer Årgang: 2016 - 2017 Fastgørelse af klimakompressor** I ovennævnte modeller er der risiko for, at holderen til klimakompressoren løsner sig og falder af. Bilfabrikanten har allerede erkendt problemet og informeret ejerne af de berørte biler. Det kan dog forekomme at ikke alle køretøjer er blevet kontrolleret eller repareret af diverse grunde. Ved servicearbejder på disse modeller skal det kontrolleres, at kompressoren sidder fast, hhv. at holderen er på plads. Følgende produktionsperioder er berørt: Jumpy IV: 20.01.2016 - 03.03.2017 Spacetourer: 07.01.2016 - 04.03.2017

## **Jumpy IV + Spacetourer**

**Model Year: 2016 – 2017**

### **Fastening the air conditioning compressor**

On the above vehicles, it is possible for the air conditioning compressor bracket to become loose and fall off.

The vehicle manufacturer has already recognized the problem and informed the affected owners. However, there is a possibility that for various reasons not all vehicles have been checked and/or repaired.

When carrying out service work on the vehicle, ensure that the compressor is firmly seated and that its bracket is firmly fastened.

The following production periods are affected.

Jumpy IV: 1/20/2016 - 3/3/2017

Spacetourer: 1/7/2016 - 3/4/2017