

Ford Transit Connect - Viskerne virker ikke | HELLA

Ford Transit Connect Årgang: 01.6.2011 - 31.10.2011
Dårlig viskerfunktion
Løse viskerarme
Viskerne virker ikke
de ovennævnte modeller kan det ske, at viskerarmene løsner sig fra viskerholderne.
Årsagen er oftest en løs ledstift, der forbinder viskerarmen med holderen. Dårlig viskerfunktion som følge af for svagt anlægstryk kan være et tegn på løse viskerarme.
Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.
Afhjælpning sker ved at udskifte de eksisterende viskerarme med ændrede viskerarme.

Transit Connect

Model year: 2011-6-1 - 2011-10-31

Poor wiper performance

Loose wiper arms

Wiper function failure

On the vehicles listed above, there may be instances where the wiper arms become loose from the wiper arm holders. This is usually caused by a loosened hinge pin that connects the wiper arm to the holder. A poor wiping pattern, due to low contact force, may be indicative of loose wiper arms.

The vehicle manufacturer has already addressed the problem and notified the owners of the affected vehicles. It must be assumed, however, that for a variety of reasons not all vehicles have been checked or repaired.

To correct this, the existing wiper arms should be exchanged for modified wiper arms.