

Kia Ceed - Airbagkontrollampen lyser | HELLA

KiaCee'dHatchback indtil stelnr.: U5YFF24428L 096498Stationcar indtil stelnr.: U5YFF23238L 006322Airbagkontrollampen lyserHvis den ovennævnte fejl påpeges af kunden, kan årsagen være en defekt stikforbindelse. Der kan også være lagt fejlkoderne f.eks. B 1353 og B 2500. En fejl på stikket på ledningsnettet kan medføre, at stikket ikke går korrekt i lås på airbagstyreenheden. I dette tilfælde skal stikket kontrolleres og evt. udskiftes. Airbagstyreenheden sidder under midterarmrænnet.Bemærk!Inden reparation skal spændingen afbrydes fra systemet i mindst 5 minutter, da der ellers er risiko for spændingsspidser. Hvis stikket er mærket med produktionsnummer „C2”, skal stikket udskiftes. Det kan bestilles med OE-artikelnr. 917101H010FFF.Ved montering af det nye stik, skal det kontrolleres, at det går korrekt i lås. Evt. fejlkoder skal slettes.

Cee'd

Hatchback VIN number: U5YFF24428L 096498

Hatchback VIN number: U5YFF23238L 006322

If a customer complains about the above error, this could be caused by a defective plug connection. The following fault codes, among others, may be stored: B 1353 and B 2500. Due to a fault on the male connector housing of the wiring harness, this is not engaging correctly in the airbag control unit. In this case, the connector must be checked and replaced if necessary. The airbag control unit is located below the centre armrest.

Caution!

When installing the new male connector housing, make sure it locks correctly. Delete the stored error codes.

Before carrying out the repair, the system must be switched to tension-free mode for at least five minutes, otherwise there is a risk of voltage peaks. If the manufacturer number "C2" is printed on the male connector housing, the male connector housing must be replaced. This can be ordered under part number 917101H010FFF.